10/074.833

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.

: 6.733,158 B2

Page 1 of 2

DATED

: May 11, 2004

INVENTOR(S): Jerry F. Fischer and John Boyer

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 4,

Lines 64-65, reads "...outwardly from each side wall 38, and a pair of spaced end wails 44 extend away from the planar wall 36 along opposite..." and should read -- ...outwardly from each side wall 38, and a pair of spaced end walls 44 extend away from the planar wall 36 along opposite... --.

Column 6.

Line 30, reads "...86 (FIG., 5) or other connector hardware (not shown) known..." and should read -- ...86 (FIG. 5) or other connector hardware (not shown) known... --.

Column 7,

Line 16, reads "...transverse to the top panel 68. A fastener 118 (FIG., 4) may..." and should read -- ...transverse to the top panel 68. A fastener 118 (FIG. 4) may... --.

Column 10,

Lines 2-3, read "1. An assembly for use in a luminaire, comprising; a ballast housing; and..." and should read -- 1. An assembly for use in a luminaire, comprising: a ballast housing; and... --.

Lines 46-47, read "11. An assembly for use in a luminaire, comprising; a ballast housing including at least on opening formed..." and should read -- 11. An assembly for use in a luminaire, comprising: a ballast housing including at least on opening formed... --.

Line 50, reads "...a fastening member operatively connected to amid ballast..." and should read -- ... a fastening member operatively connected to said

Line 62, reads "...includes a tap panel, a pair of side panels, and a pair of end..." and should read -- ...includes a top panel, a pair of side panels, and a pair of end... --.

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.

: 6,733,158 B2

Page 2 of 2

DATED

: May 11, 2004

INVENTOR(S): Jerry F. Fischer and John Boyer

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 14,

Line 7, reads "...includes a tap panel, a pair of side panels, and a pair of end..." and should read -- ...includes a top panel, a pair of side panels, and a pair of end... --

Signed and Sealed this

Seventeenth Day of May, 2005

JON W. DUDAS Director of the United States Patent and Trademark Office